ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 7 | Byatarayanapura |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0392 | 2nd Crs | Maramma Temple |
| **Segment No.** | **Total Length (m)** | |
| 7/S-W0392/S120616 | 375.54 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 375.54 | 77.599996 | 13.065146 | 77.603212 | 13.064507 | Aralimara Road | 2nd cross |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to roads and drains (Balance work) amruthahalli in Ward No 07, Byatarayanapura | 2500000 | 2017-18 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2017 - 2018 | Drain Maintenance | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | 1.Construction of RCC Drain.2.Providing RCC Covering slab. | 007-18-000080 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/BTP/WO/146/18-19 | 20/10/2018 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 04/12/2018 | 03/12/2020 | Yes |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| N.Lokanathreddy | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 7892875889 | | |

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | Pushpalatha.N.D |
| **Date of Inspection** | **Remarks** | |
| 04/12/2018 | | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|

Pushpa N.D
AE (W22)

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 7 | Byatarayanapura |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0266 | NA | Maramma Temple |
| **Segment No.** | **Total Length (m)** | |
| 7/S-W0266/S121627 | 259.16 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 259.16 | 77.599996 | 13.065146 | 77.597606 | 13.065146 | Kashinagara Main Road | W0392 |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to roads and drains (Balance work) amruthahalli in Ward No 07, Byatarayanapura | 2500000 | 2017-18 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2017 - 2018 | Drain Maintenance | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | 1.Consrtruction of RCC Drain.2.Providing and laying Covering slab. | 007-18-000080 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/BTP/WO/146/18-19 | 20/10/2018 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 04/12/2018 | 03/12/2020 | Yes |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| N.Lokanathreddy | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 7892875889 | | |

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | Pushpalatha.N.D |
| **Date of Inspection** | **Remarks** | |
| 04/12/2018 | | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|

Pushpa.N.D
AE(RZ)

**Zone:** YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0266

Date: 05/12/2018 Time: 17:30:59 RH 20181205173059